


Part No.: V111-002 & V111-001 Name: Catchfan Maxi 4m/6m Weight: See Table lbs EN 1263-1; ANSI/ASSE; A10.37-2016 & OSHA 1926.502 Material: Galvanised Steel/Aluminium Dimensions: imperial [metric]




This Technical Document must always be used in conjunction with **HAKI's General Qualifications** -See below

- 1. <u>Always</u> plan your work and installation
- 2. <u>Always</u> select the right equipment
- 3. Always regularly inspect your system



Name	Art No.	A	В	С	D	E	F	Weight [kg]
Maxi 4m	V111-002	13'-1½"	2740	10'-9 ¹⁵ ⁄ ₁₆ "	6'-6 ³ /4" ± 1'-7 ¹¹ / ₁₆ "	3'-3 ³ / ₈ " ± 9 ¹³ / ₁₆ "	~ 13'-9 ³ / ₈ "	~115
Maxi 6m	V111-001	19'-8 ¹ ⁄/"	2740	10'-9 ¹⁵ ⁄ ₁₆ "	13'-1½" ± 1'-7 ¹¹ /16"	3'-3 ³ / ₈ " ± 9 ¹³ / ₁₆ "	~ 13'-9 [%] "	~129





ITEM NO.	Part No	TITLE	QTY.	Weight (pcs)[kg]
1	V111-008	Catchfan Maxi Body 2.75m	2	16.5
2	V111-019	Catchfan Maxi - Adjustable Coupler	2	0.8
	V114-001	4.00m Profiled Inner/Outer Tube (48mm Dia)		5.8
3	OR		3	
	V1114-004	6.00m Profiled Inner/Outer Tube (48mm Dia)		8.7
4	V111-012	Catchfan Maxi Bracing Tube 4.25m	2	10
5	V113-024	Catchfan Rnd - Rnd Coupler (DF 48x48)	2	1.6
6	V111-020	Catchfan Maxi Coupler (DF 48mm x 60mm)	2	1.6
7	V111-010	Catchfan Maxi 0.80m Extension Leg	2	7
	V111-005	Catchfan Maxi 4.00m Net		13
8	OR		1	
	V111-004	Catchfan Maxi 6.00m Net		18.5
9		5.5 x 25mm x 16mm Washer Hex Head Self Drilling Screw	2	
10	V111-013	Catchfan Maxi Slab Attachment	2	4.7
11		M12 x 90mm Bolt - Stainless Steel	2	
12		M12 x 80 Bolt - Stainless Steel	8	
13		M12 Stainless Steel Nyloc Nut	10	
14	V133-082	Karabiner (6mm x 60mm)	6	
15	V114-055	7.5kN Polypropylene Rope (10mm x 220m)	1	0.2

 \wedge


* Only drop forged couplers made to EN 74 Class B should be used.

All fittings to be routinely examined. Further examinations to be undertaken after each project and following any severe weather conditions to ensure all equipment is in good condition and working order.




1. Configurations

Select attachment





+44 (0) 1227 711072






2. General Assembly



























6. Beam Attachment







7. Handling, Transport and Storage



AVOID SPARKS FROM CUTTING & WELDING



Stillage/Pallet:

- Net and Inner/Outer Tubes pre assembled (c/w carabiners)
- Body and bracing tubes pre-assembled
- Extension Legs
- Attachments, bolts and couplers (bagged)



8. Removing from service

DO NOT use catchfan after it has been subject to a load falling into it. DO NOT use catchfan if the net has not be tested in the past 12 months. DO NOT use catchfan if the metal framework is deformed, damaged or worn. DO NOT use catchfan if fixings, bolts or couplers are deformed, damaged or worn.

Remove the net from service 12 months after the last test strand has been tested. Nets removed from service should be destroyed/recycled.

Haki offers a net test strand testing service - please ask for details.



General Qualifications



These General Qualifications are applicable to HAKI products and must always be read in conjunction with each products Technical Documentation (TD).

General

- Always check general product condition before use
- If in doubt always ask by contacting a representative of HAKI
- Reject any damaged or rusty components
- HAKI products and systems provide temporary protection during construction activity.
- HAKI products are NOT tested or intended:
 - to withstand impact by any vehicle,
 - to support or provide control of the public,
 - for the containment of bulk materials.

Always plan your works

- Take note of location, proximity to permanent and temporary hazard structures.
- Take note of dimensions, layout and access areas.
- Always identify both the fall hazard for the installer and the falling materials hazard for persons and property below.
- These identified hazards should also be considered on dismantling.
- H<u>AKI</u> strongly recommends seeking competent Work at Height advice if in any doubt about the installer's or other's safety.
- Note the component weight as given on the TD sheets and ensure suitable handling equipment is available.
- Ensure local site Risk Assessment / Method Statement detail is observed and followed.

Fixing	selection
--------	-----------

- All fixings should be confirmed as suitable for the chosen application site.
- Material type and thickness, edge proximity, depth of embedment, and proximity to other fixings, all impact the strength of a fixing. Please refer to manufacturer's instructions for fixing guidance and limitation.
- The dimensions for installation and the load capacity should be confirmed by the fixing manufacturer for each application.
- Competent fixings advice should be sought if in any doubt.

Fine mesh containment

- Note that the addition of any fine containment mesh (such as on barriers or safety nets) increases the wind load attracted to the supports.
- Technical advice must be sought before any such addition.

Weather

- HAKI products and systems can be adversely impacted by significant wind speeds. Please note limitations on product TD and take any recommended remedial action. If in doubt, contact a HAKI representative.
- If in doubt, cease work, and use additional protection measures as required.
- All safety systems should be kept clear of ice and snow.

Inspection

- All installed systems should be checked at least once every 7 days by a competent person, to ensure its continued integrity and that there are no signs of any potential failing.
- We recommend that these checks are recorded in a site log.
- Please ensure any defective product identified during inspection is replaced immediately.

Loading

- Any HAKI products subjected to loading, or used in anger, should be assessed to ensure it continues to provide the necessary protection. If this involves removing from service you must ensure the area is otherwise protected.
- The system should then be fully inspected, any components replaced as necessary, and the installation confirmed as fit for continued use by a competent person.

Storage

- HAKI recommends the use of its own storage and transit solutions.
- Take careful note of lifting and loading limits.
- All components should be stored in a manner that limits any detrimental environmental effect due to weather or corrosive substances.

Traceability

• All HAKI products are traceable.

еу		
	Symbol	Meaning
1.	I	Always check / Always confirm
2.	Â	Fall Hazard
3.		Do this
4	X	Don't do this
5	Å	Be Aware
6	C	Moment Load
7		Max Wind Load
8	· 	Insert
9	Null Null	Movement / Rotation
10		Movement
11		Torque Spanner and settings
12		Tighten
13		Untighten
14		Tighten by hand
15		Concrete slab/floor/wall
16.		Shear Load
17.		Tensile Load